- (12) Japanese Unexamined (Kokai) Utility Model No. 60-112902
- (43) Published: July 31, 1985
- (54) Name of the Utility Model: Shoe
- (21) Utility Model Application No.: 58-201853
- (22) Application Filed: December 30, 1983
- (72) Author of the Utility Model: Kasatoshi Tsuchiya
- (71) Applicant: Kasatoshi Tsuchiya
- Scope of the Claims of the New Utility Model
- 1) Shoe, characterized by the fact that it is equipped with a main shoe unit, and with a cushion device using pneumatic pressure supplied in the inward direction when a high pressure status is applied in the heel unit, which is protruding at all times in the outward direction and which is provided on the shoe sole of this main shoe unit.
- 2) The shoe described in claim 1, characterized by the fact that the cushion device is deployed in the heel part on the shoe sole.
- 3) The shoe described in claim 1 or 2, characterized by the fact that the cushion device is positioned on the tiptoe side of the shoe sole.
- 4) The shoe described in claim 1 through claim 3, characterized by the fact that the cushion device comprises a concave part formed on the shoe sole of the main shoe unit, a cover unit formed with a plurality of through holes covering the opening part of this concave part, and pneumatic balls formed with a specified internal pressure, protruding from the through-holes of said cover, deployed in said concave part.
- 5) The shoe described in any of the claims 1 through 3, characterized by a construction wherein the cushion device comprises a retractable rubbing member provided on the shoe sole of the main shoe unit, wherein at least one pneumatic ball, which can be elastically deformed, is formed with a specified inner pressure.

4. Brief Explanation of Figures

Figure 1 and Figure 2 show a profile view and a plane view of the sole of the shoe indicating one embodiment of the present utility model, Figure 3 is a profile view showing the important part along the line A-A indicated in Figure 2, Figure 4 is a profile view indicating the status created when repulsive force is generated, Figure 5 and Figure 6 show a profile view and a plane view of the sole indicating a different embodiment of the present utility model, Figure 7 and Figure 8 show a profile view and a plane view of the sole indicating yet another embodiment of the present utility model, Figure 9 is an explanatory diagram showing a profile view of the important part along the line B-B indicated in Figure 8, and Figure 10 is an explanatory diagram indicating yet another embodiment of the present utility model.

1: main shoe unit,
3: heel member,
4, 4A: cushion devices
5: concave part,
7: cover,
9: rubbing member
2: shoe sole,
6: through hole,
pneumatic ball,
10: opening part

◎ 公開実用新案公報(U) 昭60-112902

@Int.Cl.4 A 43 B 13/18 21/26

庁内整理番号

❷公開 昭和60年(1985)7月31日

6670-4F 6670-4F

客查請求 未請求 (全 頁)

❷考案の名称 靴

> 迎実 昭58-201853

線別記号

顋 昭58(1983)12月30日 ❷出

土 屋 袈裟筹 土 屋 袈裟穿

東京都品川区東大井2-25-20 東京都品川区東大井2-25-20

砂代 弁理士 三浦 光康 1. 考案の名称

H

- 2. 実用析案登録請求の範囲
- 1) 靴本体と、この靴本体の靴底に備えられた常時は外方へ突出しており体質が加わると高圧状態となって内方へ投入する空圧を用いたクッション 装置とを備えたことを特徴とする靴。
- 2) クッション装置は雑底の2000年のに設けられていることを特徴とする実用新案登録請求の範囲第1項記載の報。
- 3)クッション装置は私底の爪先側の位置に設けられていることを特徴とする実用新案登録請求の 範囲第1項または第2項記載の社。
- 4)クッション装置は靴本体の靴底に形成された 凹部と、この凹部の開口部を招う複数個の透孔が 形成されたカバー体と、前記凹部内に備えられた 前記カバー体の透孔よりそれぞれ突出する複数個 の所定内圧に形成された変形可能な空圧ボールと からなることを特徴とする実用新察登録額求の範

囲第1項ないし第3項いずれかに記載の靴。

5)クッション装置は秋本体の秋底に備えられた 出役可能な援助部材と、この復動部材と前記秋底 との間に介装された少なくとも1個以上の所定内 任に形成され弾性変形の可能な空圧ボールとから 構成されていることを特徴とする実用新案登録語 求の範囲第1項ないし第3項いずれかに記載の軟。 3、考案の詳細な説明

本考察は歩行を楽にできるようにした靴に関する。

従来、歩行を楽にするため、私底を厚手の発泡性ゴム等の弾性体で形成したものがあるが、これではクッション効果があるだけで、反発する力が小さく楽に歩行することができないという欠心があった。また反発力を得るため、私底にコインのカングを備えることも考えられているが、このコイルスプリングを用いるものは寸法が大きりかつ安定性が悪く、歩行中に足を捻挫したり、くじいたりするという欠点があった。

本考察は以上のような従来の欠点に揺み、楽に

歩行できるように十分な反発力と安定状態での歩行を可能にした靴を得るにある。

以下、図面に示す実施例により本考案を詳報に 説明する。

第1図ないし第4図において、1は秋底2が間 定された稚本体である。3は前記靴本体1の靴底 2に複数個のピスで固着された難部材で、この謎 部材3にはクッション装置4が備えられている。 このクッション装置4は第2図ないし第4図に示 すように前記題部材3の先端部に形成した複数個 の凹部5と、前記鏈部材3の先端部に該先端部と の間に隙間を有するように固着された複数個の透 孔6を有するカパー体と、このカパー体7内に鎖 えられ常時は該カバー体での選孔6よりそれぞれ 突出する複数個の弾性変形可能な空圧ボール8と から構成されている。なお、空圧ボール8には押 し圧された状態で十分な反発力が発生するような 内圧があらかじめ付与されている。さらに、前記 腱部材3は複数個のピスのかわりに接着剤等で靴 底2に接着固定させてもよい。



次に第5図ないし第10図に示す本考察の異なる 実施例について説明する。なお、これらの実施例 の説明に当って、前記本考案の実施例と同一構成 部分には同一符号を付して重複する説明を省略す る。

第5回および第6回の実施例において、前記本 考案の実施例と主に異なる点は、秘底2の理部と 爪先側の位置とにクッション装置4、4を設けた 点で、このように構成することにより、靴底 2 全により大きな反発力が生じるようにでき、いっそう歩行を楽にできる。

第10図の実施例において、前記第1図ないし第 4図の実施例と主に異なる点は、空圧ボール8を カバー休7で覆うとともに、該カバー休7を疑部 材3に対し摺動可能に取付けた点で、このように 構成することによって、空圧ボール8の耐久性を

公開実用 昭和60─ 112902

向上させることができる。

以上の説明から明らかなように、本考案にあっ ては次に列挙する効果がある。

- (1) 報底に備えたクッション装置によって体重をかけると大きな反発力を発生させることができるので、歩行する場合のはね上げ力となって歩行を楽にできる。
- (2)空圧の反発力を利用しているので、反発力 を得るための寸法が小さくてすみ、従来と同様な 靴形状に形成することができる。
- (3) 構造が簡単であるので、比較的安価に製造 することができる。
- (4) 壁にクッション装置を第3図に示すように 粗込むことにより、煙を取替えるだけで本考案を 施すことができ、経済的である。
- (5) クッション装置に空圧を利用しているので、 衝撃力の吸収を効率よく行うことができる。
- 4. 図面の簡単な説明

第 1 図、第 2 図は本考案の一実施例を示す側面図、底面図、第 3 図は第 2 図のA-A線に沿う契

部断面図、第4図は反発力を付与された状態を表す断面図、第5図、第6図は本考案の異なる実施例を示す側面図、第7図、第8図は本考案の異なる実施例を示す側面図、底面図、第9図は第8図のB-B線に沿う要部断面図を示す説明図、第10図は本考案の異なる実施例を示す説明図である。

1:教本体、 2:鞋底、

3:20部材、

4、4A:クッション装置、

5:四部、 6:透孔

7:カパー対、 8:空圧ポール、


9:摺動部材、 10:開口部。

実用新案登録出顧人 土 愿 稅 拨 崁


第 2 図 2 15

空間頂頂


第 3 图




第 4 网




第 5 网




第 6 图






8




18 寒間60-11"942

第 9 図



第 10 図



19

実開60-172909

THIS PAGE BLANK (USPTO)

This Page is Inserted by IFW Indexing and Scanning Operations and is not part of the Official Record

BEST AVAILABLE IMAGES

Defective images within this document are accurate representations of the original documents submitted by the applicant.

Defects in the images include but are not limited to the items checked:
☐ BLACK BORDERS
☐ IMAGE CUT OFF AT TOP, BOTTOM OR SIDES
☐ FADED TEXT OR DRAWING
☐ BLURRED OR ILLEGIBLE TEXT OR DRAWING
☐ SKEWED/SLANTED IMAGES
☐ COLOR OR BLACK AND WHITE PHOTOGRAPHS
☐ GRAY SCALE DOCUMENTS
☐ LINES OR MARKS ON ORIGINAL DOCUMENT
☐ REFERENCE(S) OR EXHIBIT(S) SUBMITTED ARE POOR QUALITY
OTHER:

IMAGES ARE BEST AVAILABLE COPY.

As rescanning these documents will not correct the image problems checked, please do not report these problems to the IFW Image Problem Mailbox.

THIS PAGE BLANK (USPTO)